Qty:

## **Process Sheet**

: CU-DAR001 Dart Helicopters Services Job Number : 40989 -

Estimate Number : 13378

P.O. Number

This Issue : 05/08/2008

Prsht Rev. : NC First Issue : // Previous Run

Checked & Approved By

S.O. No. :

: 40317

: SMALL /MED FAB Type

08-06-18

Part Number **Drawing Number** Project Number

**Drawing Name** 

: D3772 REVA : N/A : A

: D37721

**Drawing Revision** Material Due Date

: 21/08/2008

: BACK LEG

Each

Additional Product

Written By

Comment

Job Number



: Est Rev:A

Seq. #: 1.0

Machine Or Operation: Description: M304TR1250W125

304 RD Tube 1.250 x .125w

rev.A as per dwg DD verified by:EC

Comment: Qty.: 2.3100 f(s)/Upit Total: 83.1600 f(s) 304 RD Tube 1.250 x .125w

2.0

Comment: SMALL & MEDIUM FAB RESOURCE 1

1-cut tube to lenght as per dwg D3772

2-drill holes thru on both ends of tube as per dwg D3772

FF 08/09/16 (9) 4-bend tube as per dwg D3772

3.0 QC5

INSPECT WORK TO CURRENT STEP



3- deburr

Comment: INSPECT TO CURRENT STEP

4.0 PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

			3
2			
7.:			
		4	
			57

Tuesday, 05/08/2008 2:31:20 PM Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BACK LEG

Job Number: 40989

Part Number: D37721

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

QC21

FINAL INSPECTION/W/O RELEASE

08/09/18

TION/W/O RELEASE Comment: FINAL

Job Completion



MF 08-09-18



Dart	Aerospace	Ltd
	, ioi ochdoc	

W/O: WORK ORDE			CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval
						74	
							7 19
							1

Part No: D3772-1 PAR #: WA Fault Category: Prod (Machined TOWNCR: Ves) No DQA: Date: 08/09/19


Resolution: SCIPP Disposition: QA: N/C Closed: Date: 08/09/19

NCR:4	989.	2 WC	ORK OR	DER NON-CONFORMANC	E (NCR)			11117
		Description of NC		Corrective Action Section B	Varification		7 200	
DATE STEP		Section A	Initial Action Description Chief Eng Chief Eng		Sign & Verification Section C		Approval Chief Eng	Approval QC Inspector
elglu	50	it was noticed that the total amounts of part more were not ADDM up to the correct		no replace of s	28/07/18	Saldis	EsiLE	Colodia
		Previous splits # And booking in the shop. 5 parts were found to the munual mill to be Derop. They were	hun	-> Reminp machinist to Report all scrop to ac for Dry offs.	81/20/80	Selater	house	ceder 116
		on any other whos.  - hous are not aligner and some are ovalized and front. Duranin	Lunus				hosiwa	Coolcalus


NOTE: Date & initial all entries

Sin be in a miles.

Ald with the species of the first



			1-17-190		
Tables of the Control					
and the second second			(*)		
k-					
		8			
Annual State of the Control of the C					



The second second	
	and the same of th

